**REMARKS** 

(1) Applicants' representative appreciates the Examiner about the telephone discussion on

March 8, 2005. The following remarks include applicants' separate record of the substance of that

discussion.

(2) Claims 1 and 3-8 are pending in this application, of which claims 5-8 have been added in

this Response.

(3) Claims 1, 3 and 4 were rejected under 35 U.S.C. §103(a) as being unpatentable over DE

Patent No. 3,841,203 to Obermayer et al. (Obermayer) in view of US Patent No. 5,263,444 to Prior

et al. (Prior) and further in view of US Patent No. 5,934,686 to Ottenschläger.

Claims 5-7 have been added, whose basis is found at claims 1, 3 and 4, respectively.

The Examiner tries to modify the teachings of Obermayer in view of Prior et al. and

Ottenschläger. Applicants traverse the rejection as follows.

First, there is no motivation or basis to modify Obermayer et al. in view of Ottenschläger.

The teachings of Ottenschläger are directed to jointing a crankcase 11, an oil pan 1, and an

equipment mount 13, as shown in Fig. 1. Further, the rubber elastic seal 5 is shown to be curved,

but the rubber elastic seal 5 is not taught to be U-shaped, although the Office Action states so

(Office Action, page 3, the last line). In addition, the curved rubber elastic seal 5 disclosed by

Ottenschläger joints not the crankcase halves, but the oil pan 1 to the equipment mount 13.

Although Ottenschläger teaches that the grooves 6 and the offset recesses 7 may be provided in the

crankcase 11 (col.5, lines 29-31), there is no teaching that the grooves 6 are made to form the

crankcase. Thus, the teachings of Ottenschläger are completely different from Obermayer et al.

who teach jointing the two case halves to form the crankcase.

In addition, as admitted by the Examiner, Obermayer et al. fail to disclose that the enlarged

recess is located in only one of the crankcase halves, and the enlarged recesses of Obermayer et al.

being formed on both of the case halves. Page 3, lines 8-12 of the Office Action. Prior et al. seem

to be cited for the enlarged recess or the gasket. The Examiner merely cites Ottenschläger, stating

that only one surface is taught to have a groove (7) with an enlarged recess (8). However, the

Examiner has not shown any basis to apply the teachings of Ottenschläger to joint different

members from the crank case, to Obermayer et al. There is no motivation or basis to modify

Obermayer et al. in view of Ottenschläger to provide the groove on only one of the case halves,

because Ottenschläger does not teach jointing two case halves, U-shaped seal member, nor the

merit to form the groove on only one of the joint members. Also, Obermayer et al. cannot be

modified by the teachings of Ottenschläger, at least because the symmetrical sealing piece 11 or

sealing shoulder 16 of Obermayer et al. would not be compatible with the groove formed on only

Response dated March 9, 2005

Reply to Office Action of December 9, 2004

one of the case halves.

Second, Ottenschläger is a teaching away from Obermayer et al. The teachings of

Ottenschläger are limited to be applicable for sealing the corner area of a wall element having a

right angle or at least with some angles (col. 2, line 66 to col.3, line 4). In addition, the teachings

of Ottenschläger are limited in that the grooves in the two sealing rims are not arranged in a single

common plane, but the two grooves in the two sealing rims are offset and askew relative to one

another, so that they do not intersect, are not parallel, and do not lie in the same plane, at the area

of the edge intersection of the planes of the two sealing rims (col. 2, lines 14-20). The teachings

of Ottenschläger are inconsistent with the teachings of Obermayer et al., because Obermayer et al.

teaches jointing plane surfaces of two case halves of a crank case. There is no corner in Obermayer

et al., to which Ottenschläger can be applied. Since the prior art reference must be considered in

its entirety, including disclosure of teaching away (MPEP 2141.02), the Examiner cannot rely on

Ottenschläger.

Claim 1 of the present invention recites that joint surfaces of the first and second case

halves are coupled to each other in a plane extending perpendicular to the lower end face of the

cylinder block, and that one of the joint surfaces includes a U-shaped seal groove extending along

a peripheral edge of the crank chamber. Thus, it is clear that the U-shaped seal groove of claim 1

is formed in a plane of the joint surface. Even if the body of the U-shaped seal member of the

Application No. 09/901,566

Response dated March 9, 2005

Reply to Office Action of December 9, 2004

present invention corresponds to one groove and the enlarged recess of the present invention

corresponds to another groove, the invention of claim 1 is completely different from the teaching

of Ottenschläger because the body of the U-shaped seal member of the present invention intersects

with the enlarged recess.

Regarding newly added claim 5, the U-shaped seal groove is provided on the first joint

surface, which is terminated at the enlarged recess of the present invention. It is clear that the

U-shaped seal groove of claim 5 is provided on only one plane. Even if the body of the U-shaped

seal member of the present invention corresponds to one groove and the enlarged recess of the

present invention corresponds to another groove, the invention of claim 5 is completely different

from the teaching of Ottenschläger because the body of the U-shaped seal member of the present

invention intersects with the enlarged recess.

Thus, the invention of claims 1 and 5 is not obvious over the references. Reconsideration

of the rejection is respectfully requested.

(4) Regarding added claim 8, the basis is found at Fig. 6. By the arrangement of claim 8, the

U-shaped seal member is given resiliency toward the outside wall of the groove, which makes the

U-shaped seal member biased in the groove, resulting in securing the sealing of the crankcase.

Application No. 09/901,566 Response dated March 9, 2005

Reply to Office Action of December 9, 2004

(5) In view of the above, claims 1 and 3-8 are in condition for allowance. Applicants request

such action at an early date.

If the Examiner believes that this application is not now in condition for allowance, the

Examiner is requested to contact Applicants' undersigned representative at the telephone number

indicated below to arrange for an interview to expedite the disposition of this case.

In the event that this paper is not timely filed, Applicants respectfully petition for an

appropriate extension of time. The fees for such an extension or any other fees that may be due

with respect to this paper may be charged to Deposit Account No. 50-2866.

Respectfully submitted,

WESTERMAN, HATTORI, DANIELS & ADRIAN, LLP

SY/mt

1250 Connecticut Avenue, N.W., Suite 700

Washington, DC 20036

Tel: (202) 822-1100

Fax: (202) 822-1111

Attachment: Limited Recognition

Q:\2001\010698\010698 amd-4.doc